

CUT THROUGH PERFORATION MUST IN ALL FLAPS



GTIN No. :  
Exp. Date :  
Mfg. Date :  
Batch No. :  
SR. No. :  
(Symbolical Representation of 2D)

Full flap should be unvarnished for batch details & 2D code

